

Fluke 60 Series Infrared Thermometers

FLUKE®

The professional's diagnostic tool



Fluke. Keeping your world
up and running.

Check
www.fluke.fr/applications
to find out more or download
the Application Note.



Fluke Corporation
P.O. Box 9090
Everett, WA USA 98206

Fluke Europe B.V.
P.O. Box 1186
5602 BD Eindhoven
The Netherlands

For more information call:
In the U.S.A. (800) 443-5853
or Fax (425) 446-5116
In Europe/M-East/Africa
+31 (0)40 2 675 200
or Fax +31 (0)40 2 675 222
In Canada (905) 890-7600
or Fax (905) 890-6866
From other countries
+1 (425) 446-5500
or Fax +1 (425) 446-5116

Visit us on the world wide web at:
<http://www.fluke.com>

Fluke (UK) Ltd.
52 Hurricane Way
Norwich
Norfolk
NR6 6JB
United Kingdom
Tel.: 0207 942 0700
Fax: 0207 942 0701
E-mail: industrial@uk.fluke.nl

© Copyright 2004 Fluke Corporation.
All rights reserved.
Printed in the Netherlands 08/04
Data subject to alteration without notice.
Pub ID: xxxxx-eng



Fluke 60 Series Infrared Thermometers

FLUKE®



Point, press and read temperature

The Fluke 60 Series non-contact thermometers are the ideal professional diagnostic tools for quick and accurate temperature measurements. These handheld tools are ideal for measuring surface temperatures of rotating, hard-to-reach, electricity live or dangerously hot targets like electrical motors and – panels, and heating and ventilation systems. The laser sighting system guides measurements to the right target and in less than a second, the large temperature display provides a readout of the surface temperature.

The 60 Series IR thermometers feature

- Laser guided sighting system for easy targeting with 1% accuracy
- Up to 12 points datalogging with Min, max average functions
- Up to 50:1 optical resolution
- Choice between models with fixed or adjustable emissivity
- Backlit display for easy reading in the dark
- Temperatures up to 760°C

Features

	61	63	65	66	68
Form factor	Flat grip	Pistol grip	Flat grip	Pistol grip	Pistol grip
Temperature range	-18 to 275°C	-32 to 535°C	-40 to 500°C	-32 to 600°C	-32 to 760°C
Optical resolution	8:1	12:1	8:1	30:1	50:1
Laser beam for accurate targeting	●	●	●	●	●
Backlit LCD display	●	●	●	●	●
Use selectable °C or °F	●	●	●	●	●
MIN/MAX/AVG/DIF readings		MAX only	MIN/MAX/AVG only	●	●
Datalogging			●	●	●
Hi/Lo Alarm				●	●
Adjustable emissivity				●	●

Specifications

	61	63	65	66	68
Range	-18 to 275°C	-32 to 535°C	-40 to 500°C	-32 to 600°C	-32 to 760°C
Response time	< 1 second	≤ 0.5 second	<1 second	≤ 0.5 second	≤ 0.5 second
Resolution	0.2°C	0.2°C	0.1°C to 200°C, 1°C over 200°C	0.1°C	0.1°C
Repeatability	± 2% of reading or ± 2°C*	± 0.5% or ± 1°C*	± 1% of reading or ± 1°C*	± 0.5% or ± 1°C*	± 0.5% or ± 1°C*
Accuracy: assumes ambient operating temperature of 23°C)	For targets at: -18 to -1°C: ± 3°C -1 to 275°C: ± 2% - of reading or ± 2°C*	For targets at: -32 to -26°C: ± 3°C 26 to -18°C: ± 2.5°C -18 to 23°C: ± 2°C 23°C -510°C: ± 1% of reading or ± 1°C* For targets above 510°C: ± 1.5% of reading	For targets at: -40 to 0°C: ± 5°C 0 to 100°C: ± 2°C 100 to 500°C: ± 2% of reading	For targets at: -32 to -26°C: ± 3°C -26 to -18°C: ± 2.5°C -18 to 23°C: ± 2°C For targets above 23°C: ± 1% of reading or ± 1°C*	For targets at: -32 to -26°C: ± 3°C -26 to -18°C: ± 2.5°C -18 to 23°C: ± 2°C For targets above 23°C: ± 1% of reading or ± 1°C*
Typical distance to target	Up to 1 m	Up to 2 m	Up to 1 m	5 m	8 m
Emissivity	Fixed at 0.95	Fixed at 0.95	Fixed at 0.95	Digitally adjustable from 0.1 to 1.0 by 0.01	Digitally adjustable from 0.1 to 1.0 by 0.01

* whichever is greater

Battery Life:

Fluke 66 and 68:	200 hours with laser and backlight on 50%
Fluke 65:	15 hours with laser and backlight activated
Fluke 63:	10 hours with laser and backlight activated
Fluke 61:	12 hours with laser and backlight activated

Size (HxWxD):

Fluke 63, 66 and 68:	200 mm x 160 mm x 55 mm
Fluke 65:	185 mm x 64 mm x 38 mm
Fluke 61:	184 mm x 45 mm x 38 mm

Weight:

Fluke 63, 66 and 68:	0.320 kg
Fluke 65:	0.284 kg
Fluke 61:	0.227 kg

One year warranty

Accessories and Ordering Information

Included accessories

Fluke 61, 63, 66 and 68: 9V Battery
Fluke 63, 66 and 68: Hard carrying case
Fluke 65: C50 Soft carrying case and 2 AA batteries

Ordering information

Fluke 61 Infrared Thermometer
Fluke 63 Infrared Thermometer
Fluke 65 Infrared Thermometer
Fluke 66 Infrared Thermometer
Fluke 68 Infrared Thermometer

Recommended Accessories



80PR-60



H6

